



**Design factors for a south-sloping site**  
Frequently it is not possible to obtain the ideal orientation. This is typically the case where the best views and the sun come from opposite angles or the wind comes from the same direction as the view, there is an obstruction to the solar access on the north side of the site, or the streets are not laid out to allow sections to be ideally oriented (or orientation has not been considered when the land subdivision was planned). A compromise is therefore required.

© BRANZ 2007